Saline Waste Water Treatment Plant Equipment Status Report



Form Revised $\underline{06}$ / $\underline{21}$ / $\underline{2021}$

		Form Revised 00 /21 /2021		
Equipment/Process/Resource	Status	Timeline		
Influent and Grit Removal	Yellow	Two to thirty-six months		
Comments:				
Yellow - Install automatic bar screen rake to reduce influent backup and surge (Phase I)				
Yellow - Replace influent pumps (Phase I)				
Yellow - Repair bearing on grit mechanism (Midwest CO#1; requested May 17, 2021)				
Primary Clarifiers	Green	Three to six months; ongoing		
Comments:				
Green - Regular maintenance and cleaning; target cleaning of internal components in summer 2021				
Green - Sludge pump packing replaced				
RBCs	Green	Ongoing		
Green - Regular maintenance and cleaning				
Secondary Clarifiers	Yellow	One to six months		
Yellow - Contractor selected and bid awarded for sludge pump install (Bid awarded March 2021) Green - Secondary sludge and scum line cleaning completed Yellow - Consider cover for secondary clarifiers (Phase I)				

Saline Waste Water Treatment Plant Equipment Status Report



Equipment/Process/Resource	Status	Timeline		
Digestors	Yellow	One to twenty-four months		
Comments:				
Yellow - Electrical repairs completed on flare (March 2021), repairs pending on dehumidifer/chiller Yellow - Valve replacement planned as part of sludge pump project (est. July 2021) Green - Overflow line replaced during sludge pump project (completed June 2021) Yellow - Replace existing cover (Phase I)				
Sludge Holding	Green	Ongoing		
Comments:				
Green - Regular maintenance and cleaning				
Green - Implemented new procedures to keep tanks sealed on a more frequent basis.				
Crock Improment	, p			
Bioscrubbers and Odor Control	Yellow	Two to four months		
Comments:				
Yellow - Weatherization project for bioscrubber; replace replaced non-potable water pumps (Aug-Sept 2021)				
Green - Re-acclimated organisms and maintaining appropriate pH. (Completed April 2021) Green - Boiler/heat exchange repaired and air handler functioning. (Completed March 2021)				
Tertiary Filters and UV	Yellow	Ongoing		
Comments:				
Yellow - Enhanced cleaning and maintenance of nova filters required until solids can be reduced through improvements to processes earlier in the system				
Green - All mechanical elements functioning as designed				

Status Key

Saline Waste Water Treatment Plant **Equipment Status Report**




Equipment/Process/Resource	Status	Timeline			
Human Behavior	Yellow	Three to six month			
Comments:					
Yellow - Launch a public awareness campaign to improve education on how to reduce strain on existing systems.					
Green - Created citizen odor complaint survey to track time, location, conditions of peak odor					
Effluent	Green	Ongoing			
Comments:					
Green - Currently meeting NPDES permit standards for effluent Yellow - Location and scope of work for additional chemical feed points for phosphorus removal completed implementation planned spring/summer 2021					


Additional Comments:


Updates to this report will be provided monthly.

This report is intended to be a public facing document and does not contain an engineering level of detail for the projects described. Additional questions may be directed to City Manager O'Toole at cotoole@cityofsaline.org.


NOTE: The City does not receive outside septic.








GROUND







BREATHER TO OUTSIDE





UP

TO SEC. DIGESTOR