Saline Water Treatment Plant - Equipment Status Report



Report Updated <u>09/20 /2021</u>

Equipment/Process/Resource	Status	Timeline
High Service Pumps	Green	12 to 24 months

Comments:

Green - Engineering review of third High Serve Pump in progress.

Comments:

Green - Sixty (60) RO unit membranes replaced spring 2021; additional replacements planned FY23 as part of regular maintenance. Currently analyzing performance and effectiveness.

Electrical/Communications	Yellow	6 to 18 months
---------------------------	--------	----------------

Comments:

Green - One Variable Frequency Drive replaced spring 2021; second VFD and filters to be bid as part of HSP installation project.

Yellow - Upgrading communication equipment/SCADA integration

Equipment/Process/Resource	Status	Timeline		
Building Maintenance	Yellow	6 to 12 months		
Comments:				
Yellow - Facility condition ass	essment and capital planning in	n progress		
Iron/Manganese Removal	Yellow	9 to 12 months		
Yellow - Woody overgrowth removed from infiltration basins; additional iron removal efforts to be bid winter 2021/2022. Yellow - Greensand media filter replacement to be bid (per FY22 Capital Improvement Plan); engineering review in progress.				
Water Quality	Green	Ongoing		
Comments:				
Prior month average daily hardness: August: 138 mg/l; July: 131 mg/l Winter Hardness Target: 110 to 120 mg/l Summer Hardness Target: less than 160 mg/l Prior month average daily volume: August: 1.354 MGD; July: 1.266 MGD Last hydrant flush: May 2021 (city wide) Next planned flush: Starting October 4, 2021 (city wide) Annual Water Quality Report: https://tinyurl.com/fdc5azvj Additional Comments:				